

200290" 2986600T




FIG. 3




FIG. 4

200290" 2986600T

3/33




FIG. 5




FIG. 6

200290" 2986600T

4/33




FIG. 7A




FIG. 7B

200290-298600T

5/33




FIG. 8A




FIG. 8B

200290-29866001

6/33




FIG. 8C




FIG. 8D




FIG. 8E




FIG. 8F

10099862.062003

7/33




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13

10099862-062000

8/33




FIG. 14




FIG. 15

200290 2986600F

200290" 2986600F

9/33




FIG. 16B




FIG. 16A

10/33




FIG. 17B




FIG. 17A

11/33




FIG. 20




FIG. 19




FIG. 18

200290 2986600F

12/33




FIG. 22




FIG. 24




FIG. 21




FIG. 23

200290" 2986600T

200290" 2986600T

13/33




FIG. 25




FIG. 26

14/33




FIG. 27




FIG. 28

200290" 29866001

200290" 2986600F

Docket No. 061408.3002-100
Inventors: Henschel et al
Title: Optical Fiber.....Coupler Assembly




FIG. 29




FIG. 30

200290" 2986600T

16/33




FIG. 31




FIG. 32




FIG. 33




FIG. 34

17/33




FIG. 36




FIG. 35

200290" 2986600T

200290-2936600F

18/33




FIG. 37A




FIG. 37B




FIG. 38A




FIG. 38B

19/33




FIG. 39B




FIG. 39A

200290" 2986600T

200290*2986600T

20/33




FIG. 40B

FIG. 40A




FIG. 41B




FIG. 41A

21/33




FIG. 43




FIG. 42





FIG. 44

200290" 2986600F


22/33

FIG. 45



200290" 2986600T

23/33



200290* 2986500F

24/33





FIG. 47

200290" 2986600T

200290" 2986500T

25/33



26/33




FIG. 49

1009862.062002

27/33




FIG. 50

200290 2926600T

200290" 2986600T

28/33




FIG. 51A




FIG. 51B

200290" 2986500T

30/33




FIG. 52A




FIG. 52B

200290" 2986500F




FIG. 53

200290*2986600T

33/33




FIG. 54